

General Environmental Incident Summary

Incident: 4008 **Date/Time Notice:** 1/25/2016 1339 **DEM Incident No:**

Responsible Party: Bridger Pipeline LLC

Date Incident: 1/25/2016 **Time Incident:** **Duration:**

County: McKenzie **Twp:** 152 **Rng:** 94 **Sec:** 3 **Qtr:** NW

Lat: 48.02221 **Long:** -102.70530 **Method:** Interpolation from map

Location Description: Just south of Hwy 6- northwest of the Continental Resources Rollefstad
Federal 2-3H/1-3H production batteries.

Submitted By: Bob Dundas

Affiliation: Bridger Pipeline

Address: P.O. Drawer 2360

City: Casper

State: WY

Zip: 82602

Received By:

Contact Person: Bob Dundas
P.O. Drawer 2360
Casper, WY 82602

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: 2" above ground valve set

Description of Released Contaminant: crude oil

Volume Spilled: 5.00 barrels

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: No

Cause of Incident:

A 2" valve set on our Antelope gathering pipeline failed and sprayed crude oil around the facility.

Risk Evaluation:

No risks have been identified.

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

snow and underlying soils have been impacted.

Action Taken or Planned:

A vac truck is in route and skid steer unit is onsite along with personnel. Impacted snow will be collected and temporarily placed in portable open top tank. Impacted soils will be scraped up and stockpiled on plastic until disposal authorization is obtained. While the ground is covered in snow, it is believed the release is contained on site. Adequate resources are in route and available to manage the response.

Wastes Disposal Location: to be determined.

Agencies Involved:

Updates

Date: 1/26/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Volume:

Notes:

According to the report, 5 barrels of crude oil were sprayed around the facility due to an above-ground gathering pipeline. Due to incomplete information on the location of the release, further followup is needed.

Date: 2/4/2016 **Status:** Inspection

Author: Crowdus, Kory

Updated Volume:

Notes:

On location 2/4/2016 at 12:50 p.m. Release was from an above-ground pipeline and impacted surrounding pasture land. Contaminated soils have been removed and area regraded. No remaining impacts seen at this time. Follow up in the spring to check for vegetation growth.

Date: 6/7/2016 **Status:** Inspection

Author: Crowdus, Kory

Updated Volume:

Notes:

At location 6/7/2016, at 9:51am. Vegetation is starting to grow back in patches. Further follow-up required to check on more complete growth in area.